

List of Modifications and/or Service Bulletins (Doc. P2006/154)

Applied on P2006T S/n 154

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
MOD 2006/001	1	2	S-Tec 55x Autopilot Installation	M	EASA n° 10029331	18/03/10	
MOD 2006/002	2	1	Garmin G950 Glass Cockpit	M	EASA n° 10029663	08/04/10	
MOD 2006/003	1	0	Landing Gear Switches	m	Tecnam Approval DOA n° Mod. 2006/003	02/07/09	
MOD 2006/004	1	0	Nacelle Inspection Door	m	Tecnam Approval DOA n° Mod. 2006/004	02/07/09	
MOD 2006/012	1	0	Fuel quantity sender TECNAM	m	Tecnam Approval DOA n° Mod. 2006/012	03/09/09	
MOD 2006/015	1	2	Weight Increment	M	EASA n° 10037759	21/12/11	
MOD 2006/016	1	0	Oil vent Reposition	m	Tecnam Approval DOA n° Mod. 2006/016	05/12/09	
MOD 2006/019	1	0	Winglet lamination	m	Tecnam Approval DOA n° Mod. 2006/019	17/02/10	
MOD 2006/020	1	0	Thermostatic water valve	m	Tecnam Approval DOA n° Mod. 2006/020	05/12/09	
MOD 2006/022	1	1	Retraction system hoses replacement with metal tubes	m	Tecnam Approval DOA n° Mod. 2006/022	02/12/10	
MOD 2006/023	1	0	Inspection door lower tail cone	m	Tecnam Approval DOA n° Mod. 2006/023	19/10/09	
MOD 2006/026	1	0	Oil Pressure Indicator	m	Tecnam Approval DOA n° Mod. 2006/026	08/01/10	
MOD 2006/030	1	1	Side Window	m	Tecnam Approval DOA n° Mod. 2006/030	16/09/10	
MOD 2006/031	1	0	Garmin G950 Software Update	m	Tecnam Approval DOA n° Mod. 2006/031	08/03/10	
MOD 2006/033	1	0	Vle and Vlo increment	M	EASA n° 10041602	01/10/12	
MOD 2006/034	1	0	New Landing Gear Hydraulic Pump	m	Tecnam Approval DOA n° Mod. 2006/034	06/04/10	
MOD 2006/038	2	0	Placard variation on instrument panel	m	Tecnam Approval DOA n° Mod. 2006/038	22/11/10	
MOD 2006/041	1	0	Instrument panel composite frame installation	m	Tecnam Approval DOA n° Mod. 2006/041	04/04/10	

List of Modifications and/or Service Bulletins (Doc. P2006/154)


Applied on P2006T S/n 154

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
MOD 2006/042	1	0	New aileron control lever	m	Tecnam Approval DOA n° Mod. 2006/042	14/05/10	
MOD 2006/043	1	0	New manometer on LG emergency accumulator	m	Tecnam Approval DOA n° Mod. 2006/043	14/07/10	
MOD 2006/044	1	0	New Drip tray for carburettor	m	Tecnam Approval DOA n° Mod. 2006/044	20/05/10	
MOD 2006/048	1	0	Increment of MLG joke bushing diameter	m	Tecnam Approval DOA n° Mod. 2006/048	13/07/10	
MOD 2006/049	1	5	Engine starting battery	M	EASA n° 10031750	09/09/10	
MOD 2006/050	1	0	New exhaust spring installation	m	Tecnam Approval DOA n° Mod. 2006/050	17/06/10	
MOD 2006/052	1	0	NLG design improvement (MOD.024+027+028+029)	m	Tecnam Approval DOA n° Mod. 2006/052	17/06/10	
MOD 2006/053	1	0	Control wheel rod bush	m	Tecnam Approval DOA n° Mod. 2006/053	19/05/10	
MOD 2006/054	1	0	Battery box design improvement	m	Tecnam Approval DOA n° Mod. 2006/054	02/06/10	
MOD 2006/055	1	0	Pitch trim actuator bush	m	Tecnam Approval DOA n° Mod. 2006/055	19/07/10	
MOD 2006/059	1	0	Design improvement control steering (doubler bushing)	m	Tecnam Approval DOA n° Mod. 2006/059	13/07/10	
MOD 2006/060	1	0	Design improvement for muffler manifold attachments	m	Tecnam Approval DOA n° Mod. 2006/060	22/07/10	
MOD 2006/061	1	0	Solid rivets on root leading edge	m	Tecnam Approval DOA n° Mod. 2006/061	05/08/10	
MOD 2006/062	1	0	AN bolt on NLG steering link	m	Tecnam Approval DOA n° Mod. 2006/062	07/08/10	
MOD 2006/063	1	0	New Fire Detector	m	Tecnam Approval DOA n° Mod. 2006/063	14/02/11	
MOD 2006/064	1	0	Wing air inlet design improvement	m	Tecnam Approval DOA n° Mod. 2006/064	04/10/10	
MOD 2006/065	1	0	Autopilot Master Switch placard variation	m	Tecnam Approval DOA n° Mod. 2006/065	09/09/10	

List of Modifications and/or Service Bulletins (Doc. P2006/154) **Applied on P2006T S/n 154**

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
MOD 2006/066	1	0	New Powerplant control setting layout	m	Tecnam Approval DOA n° Mod. 2006/066	20/09/10	
MOD 2006/070	1	0	Control wheel, new ergonomic design	m	Tecnam Approval DOA n° Mod. 2006/070	03/09/10	
MOD 2006/072	1	0	NLG shock absorber extension stop new configuration	m	Tecnam Approval DOA n° Mod. 2006/072	05/09/10	
MOD 2006/074	1	0	New Wing inspection cap	m	Tecnam Approval DOA n° Mod. 2006/074	04/10/10	
MOD 2006/076	1	0	Wing leading edge design improvement	m	Tecnam Approval DOA n° Mod. 2006/076	21/10/10	
MOD 2006/079	1	0	Optional Millibar scale Altimeter	m	Tecnam Approval DOA n° Mod. 2006/079	02/11/10	
MOD 2006/080	1	0	Nose Landing gear lubrication points	m	Tecnam Approval DOA n° Mod. 2006/080	08/11/10	
MOD 2006/081	1	0	Main Landing gear lubrication points	m	Tecnam Approval DOA n° Mod. 2006/081	08/11/10	
MOD 2006/082	1	0	NLG shock absorber extension stop with lubrication points	m	Tecnam Approval DOA n° Mod. 2006/082	09/11/10	
MOD 2006/084	1	0	Nose Landing gear support lubrication points	m	Tecnam Approval DOA n° Mod. 2006/084	08/11/10	
MOD 2006/085	1	0	AFT wing attachment protection cover	m	Tecnam Approval DOA n° Mod. 2006/085	12/11/10	
MOD 2006/087	1	0	Lower skin external doubler new design	m	Tecnam Approval DOA n° Mod. 2006/087	05/11/10	
MOD 2006/088	1	0	New Overvoltage Relay LAMAR	m	Tecnam Approval DOA n° Mod. 2006/088	18/10/10	
MOD 2006/090	1	0	Fuselage drainage holes	m	Tecnam Approval DOA n° Mod. 2006/090	06/12/10	
MOD 2006/091	1	0	Solid rivets on wing-box/leading edge attachment	m	Tecnam Approval DOA n° Mod. 2006/091	13/12/10	
MOD 2006/095	1	0	New inspection caps on leading edge lower camber	m	Tecnam Approval DOA n° Mod. 2006/095	15/12/10	
MOD 2006/097	1	0	W6 inspection cap design improvement	m	Tecnam Approval DOA n° Mod. 2006/097	22/12/10	

List of Modifications and/or Service Bulletins (Doc. P2006/154) **Applied on P2006T S/n 154**

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
MOD 2006/098	1	0	Solid rivets on wing root lower camber	m	Tecnam Approval DOA n° Mod. 2006/098	23/12/10	
MOD 2006/099	1	0	Leading edge ribs fittings design change	m	Tecnam Approval DOA n° Mod. 2006/099	03/01/11	
MOD 2006/100	1	0	Dripper on main door	m	Tecnam Approval DOA n° Mod. 2006/100	05/01/11	
MOD 2006/101	1	0	Airspeed system hoses replacement	m	Tecnam Approval DOA n° Mod. 2006/101	01/01/11	
MOD 2006/103	1	0	MAP hoses replacement	m	Tecnam Approval DOA n° Mod. 2006/103	15/02/11	
MOD 2006/105	1	0	Steering control lever protection	m	Tecnam Approval DOA n° Mod. 2006/105	03/02/11	
MOD 2006/109	1	0	New coolant level floating switch	m	Tecnam Approval DOA n° Mod. 2006/109	07/03/11	
MOD 2006/111	1	0	Selector valve axle material change	m	Tecnam Approval DOA n° Mod. 2006/111	12/05/11	
MOD 2006/114	1	0	Tail cone RH inspection door riveting variation	m	Tecnam Approval DOA n° Mod. 2006/114	22/06/11	
MOD 2006/120	1	1	Wing's lower skin inspection cap design improvement	m	Tecnam Approval DOA n° Mod. 2006/120	02/08/11	
MOD 2006/121	1	0	New LG emergency accumulator	M	EASA n° 10037760	21/12/11	
MOD 2006/122	1	0	GIA63W IAU p/n and Software change	m	Tecnam Approval DOA n° Mod. 2006/122	21/11/11	
MOD 2006/123	1	0	New washer on retraction compass	m	Tecnam Approval DOA n° Mod. 2006/123	12/09/11	
MOD 2006/124	1	0	No structural fiberglass bulkhead	m	Tecnam Approval DOA n° Mod. 2006/124	03/09/11	
MOD 2006/125	1	0	GDU1040 pn and Software change	m	Tecnam Approval DOA n° Mod. 2006/125	21/11/11	
MOD 2006/126	1	0	GRS77 and GDC74A software version change	m	Tecnam Approval DOA n° Mod. 2006/126	21/11/11	
MOD 2006/127	1	0	AFM 3rd edition	M	EASA n° 10037861	03/01/12	
MOD 2006/130	1	0	Engine starting battery alternative part number	m	Tecnam Approval DOA n° Mod. 2006/130	03/10/11	

List of Modifications and/or Service Bulletins (Doc. P2006/154)

Applied on P2006T S/n 154

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
MOD 2006/132	1	0	GTX33 software version change	m	Tecnam Approval DOA n° Mod. 2006/132	21/11/11	
MOD 2006/134	1	0	Rear door dripper	m	Tecnam Approval DOA n° Mod. 2006/134	20/12/11	
MOD 2006/135	1	0	Alhrs-Adc on battery bus	m	Tecnam Approval DOA n° Mod. 2006/135	19/12/11	
MOD 2006/136	1	0	Radiator attachments design improvement	m	Tecnam Approval DOA n° Mod. 2006/136	22/12/12	
MOD 2006/138	1	0	Stall warning design improvement	m	Tecnam Approval DOA n° Mod. 2006/138	05/12/11	
MOD 2006/139	1	0	Landing gear knob and plate design improvement	m	Tecnam Approval DOA n° Mod. 2006/139	10/01/12	
MOD 2006/140	1	0	Garmin G950 software version change V.0935.12	m	Tecnam Approval DOA n° Mod. 2006/140	13/01/12	
MOD 2006/141	1	0	Thermo-Tec on hot air hoses	m	Tecnam Approval DOA n° Mod. 2006/141	01/02/12	
MOD 2006/142	1	0	Retraction jack threaded terminal design improvement	m	Tecnam Approval DOA n° Mod. 2006/142	13/02/12	
MOD 2006/145	1	0	Overflow bottle alternative p/n	m	Tecnam Approval DOA n° Mod. 2006/145	20/02/12	
MOD 2006/146	1	0	Pad reinforcement plate	m	Tecnam Approval DOA n° Mod. 2006/146	23/02/12	
MOD 2006/148	1	0	UMA Trim pitch indicator	m	Tecnam Approval DOA n° Mod. 2006/148	01/06/12	
MOD 2006/149	1	0	Overvoltage system for External Power Socket	m	Tecnam Approval DOA n° Mod. 2006/149	01/06/12	
MOD 2006/150	1	0	Solid rivet on fuselage	m	Tecnam Approval DOA n° Mod. 2006/150	06/03/12	
MOD 2006/151	1	0	Anchor nut on wings	m	Tecnam Approval DOA n° Mod. 2006/151	15/03/12	
MOD 2006/152	1	0	Engine mount nuts a screws variation	m	Tecnam Approval DOA n° Mod. 2006/152	23/03/12	
MOD 2006/154	1	0	New "T" control column pulley	m	Tecnam Approval DOA n° Mod. 2006/152	14/05/12	

List of Modifications and/or Service Bulletins (Doc. P2006/154)

Applied on P2006T S/n 154

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
MOD 2006/158	1	0	Solid rivets on leading edge	m	Tecnam Approval DOA n° Mod. 2006/158	03/05/12	
MOD 2006/159	1	1	Hydraulic actuator head design improvement	m	Tecnam Approval DOA n° Mod. 2006/159	07/05/12	
MOD 2006/160	1	0	Leading edge reinforcement plate	m	Tecnam Approval DOA n° Mod. 2006/160	08/05/12	
MOD 2006/161	1	0	Flap/Engine cowlwing fitting reinforcement plate installation	m	Tecnam Approval DOA n° Mod. 2006/161	28/05/12	
MOD 2006/162	1	0	Airbox design improvement	m	Tecnam Approval DOA n° Mod. 2006/162	28/05/12	
MOD 2006/163	1	0	Propeller bowden fixture change	m	Tecnam Approval DOA n° Mod. 2006/163	29/05/12	
MOD 2006/164	1	0	Led light installation	m	Tecnam Approval DOA n° Mod. 2006/164	27/06/12	
MOD 2006/165	1	0	Chinese placard configuration	m	Tecnam Approval DOA n° Mod. 2006/165	02/07/12	
MOD 2006/166	1	0	Aileron hinges design improvement	m	Tecnam Approval DOA n° Mod. 2006/166	02/07/12	
MOD 2006/168	1	0	Fuel selector valve bowden routing variation	m	Tecnam Approval DOA n° Mod. 2006/168	02/07/12	
MOD 2006/169	1	0	New LG retraction compass	m	Tecnam Approval DOA n° Mod. 2006/169	18/07/12	
MOD 2006/171	1	0	Abs cover on first frame	m	Tecnam Approval DOA n° Mod. 2006/171	07/08/12	
MOD 2006/172	1	0	New fire extinguisher	m	Tecnam Approval DOA n° Mod. 2006/172	13/09/12	
MOD 2006/173	1	0	New NLG spring	m	Tecnam Approval DOA n° Mod. 2006/173	08/10/12	
MOD 2006/174	1	0	New shuttle valves	m	Tecnam Approval DOA n° Mod. 2006/174	08/10/12	
MOD 2006/176			Optional heating system	m	Tecnam Approval DOA n° Mod. 2006/176	04/07/13	

List of Modifications and/or Service Bulletins (Doc. P2006/154)

Applied on P2006T S/n 154

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
MOD 2006/177	1	0	New cooling silicone tubes	m	Tecnam Approval DOA n° Mod. 2006/177	15/11/12	
MOD 2006/178	1	0	Compass support	m	Tecnam Approval DOA n° Mod. 2006/178	03/12/12	
MOD 2006/179	1	0	New NLG retraction alignment system	m	Tecnam Approval DOA n° Mod. 2006/179	08/03/13	
MOD 2006/180	1	0	Bulkhead for wiring	m	Tecnam Approval DOA n° Mod. 2006/180	11/03/13	
MOD 2006/181	1	0	New NAV/POS/STROBE LED light installation	m	Tecnam Approval DOA n° Mod. 2006/181	20/03/13	
MOD 2006/182	1	0	NLG Retraction spring	m	Tecnam Approval DOA n° Mod. 2006/182	03/04/13	
MOD 2006/183	1	0	UMA rudder trim indicator	m	Tecnam Approval DOA n° Mod. 2006/183	29/03/13	
MOD 2006/184	1	0	Trim tab command design improvement	m	Tecnam Approval DOA n° Mod. 2006/184	12/03/14	
MOD 2006/192	1	0	Muffler design improvement	m	Tecnam Approval DOA n° Mod. 2006/192	07/09/13	
MOD 2006/194	1	0	Stabilator support bushing variation	m	Tecnam Approval DOA n° Mod. 2006/194	08/10/13	
MOD 2006/195	1	0	Engine mount design improvement	m	Tecnam Approval DOA n° Mod. 2006/195	10/12/13	
MOD 2006/196	1	0	Rudder Strip	m	Tecnam Approval DOA n° Mod. 2006/196	10/12/13	
MOD 2006/198	1	0	Inflight Engine Restart limitation removal	m	Tecnam Approval DOA n° Mod. 2006/198	07/01/14	
MOD 2006/199	1	0	Fuel sump rivets variation	m	Tecnam Approval DOA n° Mod. 2006/199	21/02/14	
MOD 2006/222	1	0	AFM revision for new rotax fuel pump	m	Tecnam Approval DOA n° Mod. 2006/222	15/06/14	

List of Modifications and/or Service Bulletins (Doc. P2006/154)

Applied on P2006T S/n 154

n°	Ediz.	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
MOD 2006/223	1	0	New flap indicator	m	Tecnam Approval DOA n° Mod. 2006/223	10/06/15	
MOD 2006/224	1	0	UMA airspeed indicator	m	Tecnam Approval DOA n° Mod. 2006/224	10/06/15	
MOD 2006/228	1	0	G950 COM NAV GPS power supply improvement	m	Tecnam Approval DOA n° Mod. 2006/228	23/06/15	
MOD 2006/230	1	0	Hydraulic actuator design improvement	m	Tecnam Approval DOA n° Mod. 2006/230	10/06/15	
MOD 2006/232	1	0	ELT KANNAD Installation	m	Tecnam Approval DOA n° Mod. 2006/202	05/05/15	
MOD 2006/234	1	0	Stabilator rear bell crank improvement	m	Tecnam Approval DOA n° Mod. 2006/234	20/02/15	
MOD 2006/236	1	0	Emergency accumulator seal replacement and check valve improvement	m	Tecnam Approval DOA n° Mod. 2006/236	10/06/15	
Tecnam S.B.014-CS;	1	0	Oil vent reposition	n/a	TECNAM under DOA certificate EASA.21J.335	05/01/10	
Tecnam S.B.098-CS;	1	0	Vlo and Vle increment for P2006T	n/a	TECNAM under DOA certificate EASA.21J.335	28/09/12	
Tecnam S.B.102-CS;	1	0	P2006T aileron hinge supports inspection	n/a	Approved by TECNAM under DOA certificate EASA.21J.335	03/07/12	
Tecnam S.B.110-CS;	1	0	P2006T AFM and AMM new revision	n/a	TECNAM under DOA certificate EASA.21J.335	05/11/12	
Tecnam S.B.113-CS;	1	0	Silicon Cooling hoses	n/a	TECNAM under DOA certificate EASA.21J.335	21/12/12	
Tecnam S.B.118-CS;	1	0	New LED landing/taxi light for P2006T	n/a	TECNAM under DOA certificate EASA.21J.335	11/02/13	
Tecnam S.B.120-CS;	1	0	Displayed heading check on Garmin glass cockpit	n/a	TECNAM under DOA certificate EASA.21J.335	07/03/13	
Tecnam S.B.123-CS;	1	0	New Nose Landing Gear retraction alignment system	n/a	TECNAM under DOA certificate EASA.21J.335	15/03/13	
Tecnam S.B.128-CS;	1	0	LNG Lower Link - inspection Replacement	n/a	TECNAM under DOA certificate EASA.21J.335	15/05/13	

List of Modifications and/or Service Bulletins (Doc. P2006/154)

Applied on P2006T S/n 154

n°	Ediz	Rev.	TITLE	Tipo Mod.: M (Maggiore) m (minore).	Approvazione	Data di approvazione della modifica	VISTO C.Q.
Tecnam S.B. 134-CS,	1	0	ACF-50 Use on all Tecnam Aircrafts	n/a	TECNAM under DOA certificate EASA.21J.335	14/10/13	
Tecnam S.B. 136-CS,	1	0	Fuel drain hose for new mechanical fuel pump p/n	n/a	TECNAM under DOA certificate EASA.21J.335	29/10/13	
Tecnam S.B. 145-CS,	1	0	P2006T AFM (Edition 3, Revision 3)	n/a	TECNAM under DOA certificate EASA.21J.335	21/02/14	
Tecnam S.B. 147-CS,	1	0	Exhaust Springs Set-Up.	n/a	TECNAM under DOA certificate EASA.21J.335	25/02/14	
Tecnam S.B. 150-CS,	1	1	P2006T Landing gear shuttle valves installation check	n/a	TECNAM under DOA certificate EASA.21J.335	28/04/14	
Tecnam S.B. 152-CS,	1	0	Exhaust Springs Safety wire installation	n/a	TECNAM under DOA certificate EASA.21J.335	18/04/14	
Tecnam S.B. 165-CS,	1	0	Exhaust System Anti-Seize Copper Grease Application.	n/a	TECNAM under DOA certificate EASA.21J.335	05/09/14	
Tecnam S.B. 170-CS,	1	1	P2006T Exhaust pipes inspection	n/a	TECNAM under DOA certificate EASA.21J.335	25/09/14	

Data 15/07/2015

Visto Certifying Staff Antonio Oliviero

